



An Exelon Company

Richard G. Webster, Jr.
Director
Rates and Regulatory Affairs

Telephone 215.841.4000 ext 5777
Fax 215.847.6208
www.exeloncorp.com
dick.webster@exeloncorp.com

PECO Energy Company
2301 Market Street, 515
Philadelphia, PA 19103

Mail To: 8699
Philadelphia, PA 19101-8699

January 30, 2012

RECEIVED

JAN 30 2012

PA PUBLIC UTILITY COMMISSION
SECRETARY'S BUREAU

Via Federal Express

Rosemary Chiavetta, Secretary
Pennsylvania Public Utility Commission
Commonwealth Keystone Building
400 North Street
Second Floor
Harrisburg, Pennsylvania 17120

**Re: PUC Docket No. L-00030161
Rulemaking Re Amending Electric Service Reliability Regulations at
52 Pa. Code Chapter 57**

Dear Secretary Chiavetta:

In accordance with Electric Service Reliability Regulations at 52 Pa. Code Chapter 57, enclosed are an original and six copies of PECO's 2011 Quarterly Reliability Report for the period ending December 31, 2011.

Because portions of the report contain sensitive and proprietary information, PECO is filing two versions of the report, one public and one proprietary. PECO requests that the proprietary report, which has been separated and clearly marked with a "Confidential and Proprietary" header on each page, be kept confidential, pursuant to Commission Order of March 20, 2006.

If you have any further questions regarding this matter, please call me at 215-841-5777.


Sincerely,

A handwritten signature in black ink, appearing to read "R. Webster", with a long horizontal flourish extending to the right.

cc: Office of Consumer Advocate
Office of Small Business Advocate

enclosures

**PECO Energy Company
Quarterly Reliability Report
For Period Ending December 31, 2011**



RECEIVED

JAN 30 2012

PA PUBLIC UTILITY COMMISSION
SECRETARY'S BUREAU

February 1, 2012

PECO Energy ("PECO")

Quarterly Reliability Report for the Period Ending December 31, 2011 filed with the Pennsylvania Public Utility Commission.

Submitted per Rulemaking Re: Amending Electric Service, Docket No. L-00030161 Reliability Regulations at 52 Pa.Code Chapter 57

Section 57.195(e)(1) "A description of each major event that occurred during the preceding quarter, including the time and duration of the event, the number of customers affected, the cause of the event and any modified procedures adopted in order to avoid or minimize the impact of similar events in the future."

A snowstorm on October 29, 2011 hit the PECO service territory affecting 275,710 customers. Repair crews consisted of PECO crews along with contract crews and Mutual Aid from Illinois, North and South Carolina, Kentucky, Tennessee, Maryland, and Georgia assisting in restoration efforts. PECO filed an exclusion request with the PUC on November 28, 2011. The request has been approved. Lessons learned have been conducted and emergency response processes implemented based on storm critique feedback.

Section 57.195(e)(2) "Rolling 12-month reliability index values (SAIFI, CAIDI, SAIDI, and if available, MAIFI) for the EDC's service territory for the preceding quarter. The report shall include the data used in calculating the indices, namely the average number of customers served, the number of sustained customer interruptions, the number of customers affected, and the customer minutes of interruption. If MAIFI values are provided, the report shall also include the number of customer momentary interruptions."

PECO Customers	Sustained Customer Interruptions	Sustained Customer Hours	Momentary Customer Interruptions	Sustained Customer Minutes	SAIFI	CAIDI	SAIDI	MAIFI
1,688,080	1,923,789	4,335,590	1,008,606	260,135,371	1.14	135	154	0.60

*Data reflects 12 months ending 12/31/2011

PECO Benchmarks and Rolling 12-Month Standards				
	SAIFI	CAIDI	SAIDI	MAIFI
Benchmark	1.23	112	138	N/A
Rolling 12-Month Standard	1.48	134	198	N/A

SAIFI is currently below the benchmark and standard. CAIDI is above the benchmark and standard. SAIDI is above the benchmark but below the standard established on May 7, 2004. No benchmark or standard was established for MAIFI.

CAIDI was driven above the Standard by storms, especially the February 2nd ice storm, which affected 9.7% of PECO customers, and was therefore not allowed to be excluded as a major event. CAIDI was also driven by excessive rain, which caused trees to uproot and streams to flood, impeding service restoration efforts.

Section 57.195(e)(3) "Rolling 12-month reliability index values (SAIFI, CAIDI, SAIDI, and if available, MAIFI) and other pertinent information such as customers served, number of interruptions, customer minutes interrupted, number of lockouts, and so forth, for the worst performing 5% of the circuits in the system. An explanation of how the EDC defines its worst performing circuits shall be included."

PECO's worst performing 5% circuits for 2011 were selected based on a weighted score combining customer interruptions, customer hours, SAIFI and SAIDI, due to outages on each circuit in a 12 month period. This measure is oriented toward contributions to system SAIFI, SAIDI and CAIDI, and local areas with high outage frequency or duration. In addition, circuits with a history of repeat appearance on worst performing lists were selectively included in the 5% list.

Worst circuits and the rolling 12-month reliability index values requested are shown in Appendix A.

Section 57.195(e)(4) *“Specific remedial efforts taken and planned for the worst performing 5% of the circuits as identified in paragraph (3).”*

Remedial efforts taken or planned to date for PECO’s worst performing 5% of circuits are shown in Appendix B.

Section 57.195(e)(5) *“A Rolling 12-month breakdown and analysis of outage causes during the preceding quarter, including the number and percentage of service outages, the number of customers interrupted, and customer interruption minutes categorized by outage cause such as equipment failure, animal contact, tree related, and so forth. Proposed solutions to identified service problems shall be included.”*

12 Months Ending December 31, 2011					
Cause	Service Outages	% of Service Outages	Customer Interruptions	% of Customer Interruptions	Customer Minutes
Animal	894	6.5%	35,587	1.8%	3,236,246
Contact/Dig-In	89	0.6%	12,052	0.6%	1,298,101
Equipment Failure	5,043	36.6%	634,913	33.0%	76,711,532
Lightning	799	5.8%	118,894	6.2%	15,814,947
Other	1,922	14.0%	209,474	10.9%	19,844,697
T&S	30	0.2%	78,261	4.1%	9,156,036
Unknown	763	5.5%	122,075	6.3%	15,539,617
Vegetation-Broken/Uprooted	2,473	18.0%	454,903	23.6%	77,745,355
Vegetation-Ingrowth	1,375	10.0%	154,672	8.0%	31,987,816
Vehicles	384	2.8%	103,494	5.4%	8,857,304

*The data supplied is the number of interrupted customers for each interruption event summed for all events, also known as customer interruptions. A customer interrupted by three separate trouble cases represents three customer interruptions, but only one customer interrupted.

The largest contributors to customer interruptions were equipment failure and tree-related interruptions. The leading groups within the equipment failure category were aerial equipment and underground equipment. Most customer interruptions caused by trees came from broken branches and tree trunks or uprooted trees (23.6% of all outages), as opposed to ingrowth (8.0% of all outages). PECO has continued with the significant supplemental vegetation management program it began in 2006 to prune or remove trees between cycles of its regularly scheduled vegetation management program.

Section 57.195(e)(6). “Quarterly and year to date information on progress toward meeting transmission and distribution inspection and maintenance goals /objectives” (For First, Second and Third Quarter reports only).”

Data not required for 4th quarter report

Section 57.195(e)(7). “Quarterly and year-to-date information on budgeted versus actual transmission and distribution operation and maintenance expenditures in total and detailed by the EDC'S own functional account code or FERC account code as available.” (For first, second and third quarter reports only.)

Data not required for 4th quarter report

Section 57.195(e)(8). “Quarterly and year-to-date information on budgeted versus actual transmission and distribution capital expenditures in total and detailed by the EDC'S own functional account code or FERC account code as available.” (For first, second and third quarter reports only.)

Data not required for 4th quarter report

Section 57.195(e)(9). “Dedicated staffing levels for transmission and distribution operation and maintenance at the end of the quarter, in total and by specific category (e.g., lineman, technician and electrician).”

PECO's full-time trade staff as of December 31, 2011 was as follows:

Aerial Lineman	390
Underground Lineman (Include UTS)	57
Transmission / Substation Mechanics, Operators	98
Energy Technicians	97
Energy Technicians Foreman	5
Aerial Foreman	64
Underground Foreman (Includes UTS)	17
Transmission / Substation Foreman	30
Total	753

Contact Persons:

J. Coffman
Director, Engineering
(215) 841-4201
jearl.coffman@peco-energy.com

Dick Webster
Director, Rates and Regulatory
(215) 841-5777
dick.webster@peco-energy.com

Appendix A
Rolling 12- month reliability index values for 5% worst performing circuits

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
ABINGTON_004	177	2.15	232	498	1.00	380	1,468	177
BELLEVUE_002	765	1.32	225	296	1.00	1,006	3,769	765
BRADFORD_341	1,592	1.32	152	201	4.46	2,103	5,340	7101
BRADFORD_342	2,272	1.66	89	147	0.84	3,779	5,578	1912
BRADFORD_346	2,312	2.68	132	354	1.50	6,185	13,623	3465
BRADFORD_352	993	2.59	122	315	0.95	2,570	5,207	941
BRADFORD_353	1,140	2.51	109	273	1.99	2,860	5,196	2273
BRYAN_002	395	0.25	414	104	0.04	99	682	17
BRYN_MAWR_132	1,105	1.38	133	183	0.00	1,520	3,375	0
BUCKINGHAM_346	2,532	1.61	151	244	1.03	4,083	10,294	2596
BUCKINGHAM_351	1,832	5.13	185	951	0.71	9,398	29,023	1301
BUCKINGHAM_352	2,179	2.35	154	362	2.62	5,122	13,159	5707
BUCKINGHAM_353	1,388	3.73	126	469	0.70	5,173	10,844	967
BURHOLME_014	160	4.48	216	967	0.00	716	2,579	0
BURHOLME_132	853	1.41	72	102	0.00	1,206	1,447	0
BYBERRY_148	1,888	1.57	120	188	0.07	2,956	5,914	138
BYBERRY_160	1,472	1.76	146	258	0.00	2,593	6,324	0
BYBERRY_173	1,649	1.88	67	126	0.34	3,106	3,467	560
CARMEL_004	579	0.98	385	379	1.00	570	3,654	579
CARVER_000	368	3.33	494	1648	0.00	1,227	10,106	0
CEDARBROOK_131	1,015	0.64	407	260	0.00	649	4,406	0
CHICHESTER_137	2,054	1.42	41	59	0.00	2,918	2,006	0
CHURCH_004	455	0.42	70	29	3.49	192	223	1586
CIVIC_010	246	1.72	185	318	0.00	422	1,302	0
CLAY_342	2,384	3.55	343	1219	1.83	8,472	48,446	4358
CURLY_000	564	5.33	188	1001	3.00	3,007	9,414	1692
DOWNINGTOWN_003	982	2.06	16	32	2.96	2,024	526	2908
DOYLESTOWN_003	694	3.85	158	609	2.00	2,669	7,043	1388
DURHAM_002	588	3.25	127	413	1.00	1,912	4,045	589
EAGLE_352	1,590	3.75	127	477	1.76	5,965	12,637	2799
FALLS_011	323	0.04	105	4	0.00	12	21	0
FALLS_341	986	1.58	187	296	0.00	1,556	4,857	0
FIN_002	451	1.25	181	226	0.00	562	1,700	0
FLINT_131	451	1.14	137	157	0.00	516	1,180	0
FLINT_147	162	1.28	264	338	0.00	208	914	0
FOULK_131	1,702	6.24	118	736	1.87	10,615	20,864	3190
FOULK_133	1,474	1.03	77	79	0.00	1,517	1,952	0
FOX_CHASE_131	1,709	1.07	112	120	0.00	1,825	3,409	0
FOX_CHASE_134	948	0.53	94	50	0.66	504	793	623
FURNACE_000	570	1.17	376	440	0.00	667	4,182	0
GLADWYNE_138	479	3.42	122	416	0.21	1,638	3,322	101
GOLF_001	695	3.00	194	582	3.08	2,086	6,740	2140
GOLF_002	537	2.89	132	380	1.00	1,552	3,403	537
GRAVEL_002	459	0.12	716	86	1.00	55	657	459
GROVE_000	640	1.11	224	249	1.00	712	2,656	640
HANOVER_003	600	7.32	166	1212	1.17	4,390	12,123	703
HEARTWOOD_001	586	2.45	335	822	1.00	1,438	8,033	586
HOWELL_002	391	6.53	147	957	5.31	2,554	6,238	2076

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
HUNTING_PARK_048	907	2.38	104	248	0.00	2,163	3,747	0
JARRETT_132	950	1.44	248	358	0.94	1,371	5,674	892
JARRETT_144	1,160	6.39	127	811	0.41	7,411	15,683	475
JORDAN_002	434	0.43	96	42	0.00	187	300	0
LENAPE_000	476	0.63	292	185	0.06	302	1,469	28
LINE_131_00WO	545	1.16	226	263	0.00	634	2,390	0
LINE_149_00	1,013	0.27	203	56	1.80	278	941	1820
LINE_161_00CO	1,225	2.91	183	531	0.03	3,562	10,842	39
LINE_175_00CO	339	3.05	127	387	0.02	1,035	2,184	7
LINE_183_00	721	0.27	135	37	1.02	196	440	734
LINE_2206	4	0.00	0	0	0.00	0	0	0
LINE_2252	278	1.01	47	47	0.00	280	218	0
LINE_2672	70	1.03	105	108	0.01	72	126	1
LINE_2682	1,846	0.40	119	48	0.00	747	1,476	0
LINE_3307NT	1,782	1.04	147	154	0.59	1,857	4,564	1060
LINE_6000	16	3.94	157	619	0.00	63	165	0
LINE_9600	454	3.08	129	397	2.00	1,400	3,005	906
LOMBARD_032	205	2.11	121	255	0.00	433	872	0
LOMBARD_043	330	4.59	129	590	0.24	1,514	3,245	79
MACDADE_136	2,467	0.74	75	55	0.00	1,824	2,274	0
MAIN_000	131	4.30	280	1205	0.00	563	2,631	0
MARPLE_003	436	4.02	384	1542	1.00	1,752	11,208	436
MIDDLETOWN_352	2,323	2.84	157	447	2.78	6,606	17,294	6449
MORGAN_001	246	2.85	147	418	1.00	701	1,714	246
MORGAN_002	370	4.80	249	1194	1.00	1,775	7,363	370
MORRISVILLE_012	832	1.20	113	136	1.16	998	1,881	969
MORTON_133	782	3.59	239	860	0.00	2,809	11,209	0
MORTON_142	1,308	4.43	129	572	0.56	5,795	12,473	728
MORWOOD_000	689	1.44	118	170	0.00	993	1,949	0
NEW_HOPE_001	515	1.29	177	227	6.00	663	1,952	3091
NEW_HOPE_002	704	1.25	160	201	6.00	882	2,353	4221
NEWLINVILLE_343	2,556	1.39	85	118	1.18	3,547	5,042	3008
NEWTOWN_SQUAR_131	1,310	5.06	106	536	1.31	6,635	11,704	1716
NEWTOWN_SQUAR_133	683	3.99	145	577	1.42	2,723	6,569	973
NEWTOWN_SQUAR_134	658	5.30	135	715	1.25	3,489	7,837	820
NEWTOWN_SQUAR_146	1,153	1.66	171	283	0.00	1,909	5,443	0
NICE_001	157	2.31	67	156	0.00	363	407	0
NORCO_001	425	2.15	45	97	1.00	912	688	425
NORTH_WALES_347	855	1.09	99	107	0.99	930	1,531	849
PENCOYD_134	221	3.09	101	311	0.00	682	1,146	0
PIKE_041	1,180	0.16	99	16	0.00	185	307	0
PLANEBROOK_351	1,238	3.82	177	678	1.76	4,734	13,983	2177
PLUMSTEAD_001	331	3.13	168	527	0.00	1,036	2,908	0
PULASKI_014	966	0.87	108	94	0.00	841	1,508	0
ROXBOROUGH_136	1,154	1.80	69	123	0.00	2,077	2,373	0
SCOTT_002	291	0.04	411	17	0.00	12	82	0
SHEEDER_000	438	3.88	196	761	2.94	1,700	5,559	1288
SOLEBURY_002	320	3.95	248	978	1.98	1,263	5,216	633
SPROUL_002	652	2.94	80	235	2.00	1,917	2,551	1304
STONY_001	403	1.55	211	326	1.00	624	2,192	402
STOTTSVILLE_000	490	4.16	91	380	0.00	2,039	3,105	0

CIRCUIT	CUSTOMERS ON CIRCUIT	12 Month Rolling Circuit SAIFI	12 Month Rolling Circuit CAIDI	12 Month Rolling Circuit SAIDI	12 Month Rolling Circuit MAIFI	12 Month Rolling Customers Interrupted	12 Month Rolling Customer Hours	12 Month Rolling Momentary Customers Interrupted
SUNNYBURN_001	460	0.37	351	128	0.02	168	982	9
TREDYFFRIN_341	641	0.00	0	0	0.00	0	0	0
TUNA_141	588	0.01	145	1	0.00	5	12	0
UNIVERSITY_011	368	2.00	110	220	0.00	737	1,352	0
UPPER_DARBY_132	1,648	0.10	129	13	0.00	172	370	0
UPPER_MERION_351	2,693	2.76	136	374	0.04	7,424	16,787	121
WAYNE_134	677	2.57	122	314	2.39	1,743	3,546	1615
WAYNE_136	869	2.93	112	327	2.60	2,546	4,737	2259
WEST_BUCK_001	244	1.13	191	215	4.00	275	875	976
WHITEMARSH_141	1,048	3.08	117	360	0.69	3,230	6,280	724
WICKER_002	154	3.34	179	599	0.99	515	1,537	153
WOODBOURNE_352	649	2.06	300	618	0.32	1,338	6,685	206
WRIGHT_000	404	1.47	158	232	0.01	592	1,560	4
WYNCOTE_003	210	3.07	146	448	0.00	645	1,567	0
YEADON_134	1,821	0.22	299	66	0.00	401	1,998	2

The data supplied is the number of interrupted customers for each interruption event summed for all events, also known as customer interruptions. If a customer is interrupted by three separate trouble cases, they represent three customer interruptions, but only one customer interrupted.

Appendix B

Remedial efforts taken and planned for 5% worst performing circuits as of 12/31/11

ABINGTON_004

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Completed regularly schedule tree trimming

Planned:

Remedial efforts completed

BELLEVUE_002

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Planned:

Remedial efforts completed

BRADFORD_341

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective workorders

Installed 3-three phase reclosers

Planned:

Remedial efforts completed

BRADFORD_342

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed 2-three phase reclosers

Installed additional fusing

Planned:

Remedial efforts completed

BRADFORD_346

Chester County

Completed

Completed reliability corrective work orders

Installed animal protection

Tested/Inspected recloser operation

Installed three phase recloser

Upgraded transformer

Installed additional lightning protection

Performed regularly schedule tree clearance

Inspected selected areas of circuit for vegetation issues and corrected as needed

Inspected circuit visually and with thermographic camera

Upgraded fuses

Planned

Remedial efforts completed

BRADFORD_352

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Inspected/ Tested switch operation

Planned

Remedial efforts completed

BRADFORD_353

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed three phase recloser

Completed reliability corrective work orders

Planned

Remedial efforts completed

BRYAN_002

York County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Installed additional fuses

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed lightning protection

Planned:

Remedial efforts completed.

BRYN_MAWR_132

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Planned

Remedial efforts completed

BUCKINGHAM_346

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective work orders
Upgraded transformers
Upgraded primary wires
Upgraded underground wires
Installed additional lightning protection
Installed additional fuses

Planned

Remedial efforts completed

BUCKINGHAM_351

Bucks County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Upgraded transformer
Repaired / tested switch operation
Installed additional lightning protection
Installed 3-phase recloser
Performed regularly schedule tree clearance

Planned:

Remedial efforts completed

BUCKINGHAM_352

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective work orders
Upgraded transformer
Inspected/Tested recloser operation

Planned

Remedial efforts completed

BUCKINGHAM_353

Bucks County

Completed:

Complete reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Installed additional lightning protection
Upgraded secondary wires

Planned

Remedial efforts completed

BURHOLME_014

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Tested/ Inspected switch operation

Reconfigured station leg cable

Completed reliability corrective work orders

Replaced cable

Installed switch

Installed wildlife protection

Planned

Remedial efforts completed

BURHOLME_132

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Installed additional fuses

Upgraded lightning protection

Installed 3-3 phase reclosers

Planned

Remedial efforts completed

BYBERRY_148

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Upgraded secondary wires

Upgraded transformer

Install 1 phase recloser

Planned

Remedial efforts completed.

BYBERRY_160

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Upgraded transformer

Upgraded fuses

Upgraded cable insulation

Planned

Remedial efforts completed

BYBERRY_173

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed three phase recloser
Checked/ tested recloser operation
Installed additional animal protection
Installed compact single phase recloser

Planned:

Remedial efforts completed.

CARMEL_004

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective work orders
Installed tree wire
Upgraded transformer
Installed additional fuses
Tested recloser operation

Planned

Remedial efforts completed

CARVER_000

Bucks County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective work orders
Upgraded transformer
Installed animal protection
Inspected select areas of circuit for vegetation issues and correct as needed

Planned

Remedial efforts completed

CEDARBROOK_131

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Completed reliability corrective work orders
Upgraded secondary wires

Planned

Remedial efforts completed

CHICHESTER_137

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Upgraded cable insulation

Upgraded lightning protection

Upgraded secondary wires

Installed 3 phase recloser

Planned

Remedial efforts completed

CHURCH_004

Delaware County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

CIVIC_010

Philadelphia County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Replaced underground cable

Upgraded fuse coordination

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

CLAY_342

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional lightning protection

Installed additional fusing

Replaced cable

Installed animal protection

Upgraded wire

Check/ test recloser operation

Planned:

Remedial efforts completed

CURLY_000

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

DOWNINGTOWN_003

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

DOYLESTOWN_003

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed 3-phase recloser

Upgraded service wire

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

DURHAM_002

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Planned:

Remedial efforts completed

EAGLE_352

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed 2- 3 phase reclosers

Complete regularly scheduled tree trimming

Planned:

Remedial efforts completed

FALLS_011

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

FALLS_341

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

FIN_002

York County

Completed

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Upgraded fuses

Inspected selected areas of circuit for vegetation issues and corrected as needed

Planned

Remedial efforts completed

FLINT_131

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Performed regularly scheduled tree clearance

Inspected selected areas of circuit for vegetation issues and corrected as needed

Planned:

Remedial efforts completed

FLINT_147

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed animal protection

Installed additional fuses

Install single phase recloser

Planned:

Remedial efforts completed

FOULK_131

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed additional lightning protection

Installed additional fuses

Installed (3) three phase reclosers

Planned:

Remedial efforts completed

FOULK_133

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and corrected as needed

Installed additional fuses

Planned:

Remedial efforts completed

FOX CHASE_131

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Upgraded lightning protection

Installed additional fuses

Planned:

Remedial efforts completed

FOX CHASE_134

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional fuses

Completed reliability corrective workorders

Replaced aerial cable

Planned:

Remedial efforts completed

FURNACE_000

York County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and corrected as needed

Completed reliability corrective work orders

Installed 3 phase recloser

Installed additional fusing

Upgraded fuse coordination

Planned:

Remedial efforts completed

GLADWYNE-138

Delaware County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed 3 phase recloser

Planned:

Remedial efforts completed

GOLF_001

Chester County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed additional fuses

Planned:

Remedial efforts completed

GOLF_002

Chester County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed faulted circuit indicators

Installed additional fuses

Planned:

Remedial efforts completed

GRAVEL_002

Bucks County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Planned:

Remedial efforts completed

GROVE_000

Chester County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed 2-3phase reclosers on supply circuit

Installed additional fuses

Planned:

Remedial efforts completed

HANOVER_003

Bucks County

Completed:

- Completed reliability corrective work orders
- Upgraded aerial wire
- Upgraded transformer
- Inspected circuit visually and with thermographic camera
- Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

HEARTWOOD_001

Bucks County

Completed:

- Inspected circuit visually and with thermographic camera
- Completed reliability corrective work orders
- Installed additional fuses

Planned:

Remedial efforts completed

HOWELL_002

Chester County

Completed:

- Completed reliability corrective work orders
- Inspected selected areas of circuit for vegetation issues and correct as needed
- Inspected circuit visually and with thermographic camera
- Completed regularly schedule tree trimming

Planned:

Remedial efforts completed

HUNTING_PARK_048

Philadelphia County

Completed:

- Completed reliability corrective work orders
- Inspected selected areas of circuit for vegetation issues and correct as needed
- Inspected circuit visually and with thermographic camera
- Installed additional lightning protection
- Upgraded fusing
- Inspected selected areas of circuit for vegetation issues and correct as needed

Planned

Remedial efforts completed

JARRETT_132

Montgomery County

Completed:

- Completed reliability corrective work orders
- Inspected selected areas of circuit for vegetation issues and correct as needed
- Inspected circuit visually and with thermographic camera

Planned:

Remedial efforts completed

JARRETT_144

Montgomery County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Completed regularly schedule tree trimming
Installed 2-3 phase reclosers
Upgraded wire

Planned:

Remedial efforts completed

JORDAN_002

Montgomery County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Upgraded wires
Upgraded transformers

Planned:

Remedial efforts completed

LENAPE_000

Chester County

Completed:

Inspected selected areas of circuit for vegetation issues and correct as needed
Inspected circuit visually and with thermographic camera
Completed reliability corrective work orders
Installed additional fusing

Planned:

Remedial efforts completed

LINE_131-00W0

Bucks County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

LINE_149_00

Chester County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional lightning protection
Upgraded fuse coordination
Tested/ Inspected switch operation
Installed 3-phase recloser

Planned:

Remedial efforts completed

LINE_161_00CO

Chester County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional lightning protection
Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

LINE_175_00CO

Chester County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and corrected as needed
Upgraded secondary wires
Installed lightning protection
Installed 3 phase reclosers
Tested/Inspected switch operation
Performed regularly schedule tree clearance

Planned:

Remedial efforts completed

LINE_183_00

Bucks County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

LINE_2206

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Inspected circuit visually and with thermographic camera
Upgraded transformer
Installed additional fuses
Upgraded lightning protection

Planned:

Remedial efforts completed

LINE_2252

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and correct as needed
Inspected circuit visually and with thermographic camera
Replaced underground cable

Planned:

Remedial efforts completed

LINE_2672

Philadelphia County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Replace underground cable

Planned:

Remedial efforts completed

LINE_2682

Philadelphia County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Upgraded lightning protection

Installed additional fuses

Performed regularly scheduled tree trimming

Planned:

Remedial efforts completed

LINE_3307NT

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Performed regularly scheduled tree clearance

Installed additional fuses

Installed additional lightning protection

Inspected selected areas of circuit for vegetation issues and corrected as needed

Planned:

Remedial efforts complete

LINE_6000

Bucks County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed capacitor

Planned:

Remedial efforts completed

LINE_9600

Montgomery County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

LOMBARD_032

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed reliability corrective work orders

Installed recording /testing devices

Planned:

Remedial efforts completed

LOMBARD_043

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed reliability corrective work orders

Replaced transformer

Upgraded underground cable

Planned:

Remedial efforts completed

MACDADE_136

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed animal protection

Completed regularly scheduled tree trimming

Planned

Remedial efforts completed

MAIN_000

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional fuses

Reconfigured circuit

Completed regularly scheduled tree trimming

Planned

Remedial efforts completed

MARPLE_003

Philadelphia County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned

Remedial efforts completed

MIDDLETOWN_352

Delaware County

Completed:

Performed regularly scheduled tree clearance
Inspected circuit visually and with thermographic camera
Completed reliability corrective work orders
Upgraded cable insulation
Inspected selected areas of circuit for vegetation issues and corrected as needed
Installed additional lightning protection
Installed 3 phase recloser
Performed regularly schedule tree clearance

Planned:

Remedial efforts completed

MORGAN_001

Bucks County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed

Planned

Remedial efforts completed

MORGAN_002

Bucks County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional fuses
Upgraded wires

Planned

Remedial efforts completed

MORRISVILLE_012

Bucks County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional lightning protection

Planned

Remedial efforts completed.

MORTON_133

Delaware County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Performed regularly scheduled tree clearance
Installed wildlife protection
Inspected selected areas of circuit for vegetation issues and correct as needed
Completed regularly scheduled tree trimming

Planned

Remedial efforts completed

MORTON_142

Delaware County

Completed

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Performed regularly scheduled tree clearance

Planned:

Remedial efforts completed

MORWOOD_000

Montgomery County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional fuses

Upgraded transformer

Planned

Remedial efforts completed

NEW_HOPE_001

Bucks County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed additional fuses

Upgraded transformer

Planned:

Remedial efforts completed

NEW_HOPE_002

Bucks County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Upgraded wires

Planned:

Remedial efforts completed

NEWLINVILLE_343

Chester County

Completed:

Completed reliability corrective work orders

Tested/Inspected recloser operation

Inspected circuit visually and with thermographic camera

Upgraded fusing

Installed additional lightning protection

Installed 3 phase recloser

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_131

Delaware County

Completed:

Completed reliability corrective work orders
Tested/Inspected recloser operation
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Upgraded fuse coordination
Installed compact 1 phase recloser
Installed 2 - 3 phase reclosers
Installed tree resistant spacer cable
Installed additional animal protection

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_133

Delaware County

Completed:

Inspected circuit visually and with thermographic camera
Completed reliability corrective work orders
Inspected selected areas of circuit for vegetation issues and corrected as needed
Installed additional transformer

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_134

Delaware County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Installed 3 phase recloser
Installed additional fuses

Planned:

Remedial efforts completed

NEWTOWN_SQUARE_146

Delaware County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Replaced underground cable
Updated recloser communication settings

Planned

Remedial efforts completed

NICE_001

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional fuses

Planned:

Remedial efforts completed

NORCO_001

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Installed additional fuses

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned

Remedial efforts completed

NORTH_WALES_347

Montgomery County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Installed switch

Planned:

Remedial efforts completed

PENCOYD_134

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed reliability corrective work orders

Upgraded transformer

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

PIKE_041

Philadelphia County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Upgraded lightning protection

Installed additional fuses

Planned:

Remedial efforts completed

PLANEBROOK_351

Chester County

Completed

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Installed additional animal protection

Tested/Inspected recloser operation

Repaired switch

Planned

Remedial efforts completed

PLUMSTEAD_001

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed.

PULASKI_014

Philadelphia County

Completed

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional fuses

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

ROXBOROUGH_136

Philadelphia County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Tested/Inspected recloser operation

Installed additional fuses

Installed 3 phase recloser

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

SCOTT_002

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected/Tested recloser operation

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

SHEEDER_000

Chester County

Completed:

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed 3 phase recloser

Installed additional fuses

Installed additional transformer

Installed faulted circuit indicators

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

SOLEBURY_002

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

SPROUL_002

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Tested Inspected recloser operation

Replaced switch

Installed additional fuses

Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

STONY_001

Bucks County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed reliability corrective work orders

Installed additional fuses

Planned:

Remedial efforts completed.

STOTTSVILLE_000

Chester County

Completed:

Inspected circuit visually and with thermographic camera

Completed reliability corrective work orders

Installed additional fuses

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

SUNNYBURN_001

York County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Installed additional lightning protection

Installed additional fuses

Installed 3 phase recloser on supply circuit

Planned:

Remedial efforts completed

TREDDYFRIN_341

Chester County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Upgrade fuse coordination
Installed 3 phase recloser
Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

TUNA_141

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Installed additional fuses
Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

UNIVERSITY_011

Philadelphia County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

UPPER_DARBY_132

Delaware County

Completed:

Completed reliability corrective work orders
Performed regularly schedule tree clearance
Inspected circuit visually and with thermographic camera
Inspect selected areas of circuit for vegetation issues and correct as needed
Installed 3 phase recloser
Installed additional fuses

Planned:

Remedial efforts completed

UPPER_MERION_351

Montgomery County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Tested/Inspected recloser operation
Tested/Inspected switch operation
Completed regularly scheduled tree trimming

Planned:

Remedial efforts completed

WAYNE_134

Delaware County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Tested / Inspected recloser operation
Installed heavy duty tree wire
Installed 3-1 phase reclosers

Planned:

Remedial efforts completed

WAYNE_136

Delaware County

Completed:

Completed reliability corrective work orders
Inspected circuit visually and with thermographic camera
Installed three phase reclosers
Installed tree resistant spacer cable

Planned:

Remedial efforts completed.

WEST_BUCK_001

Bucks County

Completed

Inspected circuit visually and with thermographic camera
Completed reliability corrective work orders
Installed 3 phase recloser on supply circuit
Upgraded secondary wires

Planned:

Remedial efforts completed

WHITEMARSH_141

Montgomery County

Completed:

Inspected circuit visually and with thermographic camera
Inspected selected areas of circuit for vegetation issues and correct as needed
Completed reliability corrective work orders
Replaced underground cable
Installed compact 1 phase recloser
Installed three phase reclosers
Tested recloser operation
Installed animal protection
Upgraded fusing

Planned:

Remedial efforts completed

WICKER_002

Chester County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Planned:

Remedial efforts completed

WOODBOURNE_352

Bucks County

Completed:

Completed reliability corrective work orders

Inspected circuit visually and with thermographic camera

Planned:

Remedial efforts completed

WRIGHT_000

Bucks County

Completed

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Upgraded transformer

Planned:

Remedial efforts completed

WYNCOTE_003

Montgomery County

Completed

Completed reliability corrective work orders

Inspected selected areas of circuit for vegetation issues and correct as needed

Inspected circuit visually and with thermographic camera

Installed tree wire

Planned:

Remedial efforts completed

YEADON_134

Delaware County

Completed:

Inspected circuit visually and with thermographic camera

Inspected selected areas of circuit for vegetation issues and correct as needed

Completed reliability corrective work orders

Performed regularly schedule tree clearance

Tested/Inspected recloser operation

Upgraded transformer

Installed additional animal protection

Upgraded lightning protection

Planned:

Remedial efforts completed

Appendix C

New Business Connections

This work category includes all the facility work required to add a new customer or to increase the load to an existing customer. The facility work will include the facilities required to directly connect the customer to the system and the upgrade/replacement of any existing facility to serve the requested additional load.

Capacity Expansion

This work category includes only capacity work generated by the system design engineer to prevent system failure and to assure the delivery of voltage as specified in the tariff. The addition of new substations and substation enlargements for future load growth will also be included in this project.

System Performance

This work category includes projects designed to upgrade, modify or improve the performance of the distribution system. Also included in this category are indirect costs in support of all categories and one-time accounting adjustment items.

Facility Relocation

This work category includes all requests for relocation of PECO facilities including municipal as well as customer related relocation requests.

Maintenance

This work category includes work performed to repair and restore equipment to its normal state of operation, along with planned preventive maintenance work such as visual and thermographic inspections and tree trimming around transmission and distribution lines.

Storm Funds

Incremental costs (primarily; overtime, contractors, mutual assistance, and meals) incurred while responding to major storms (storms that meet customer outage and duration criteria).

From: (215) 841-5776
Anna Migliaccio
Exelon
2301 Market Street S15-2

Philadelphia, PA 19103

Origin ID: REDA



Ship Date: 30JAN12
ActWgt: 1.0 LB
CAD: 9876187/NET3250

Delivery Address Bar Code



SHIP TO: (717) 772-7777 BILL SENDER
Rosemary Chiavetta, Secretary
Pa Public Utility Commission
400 NORTH ST FL 2
COMMONWEALTH KEYSTONE BLDG
HARRISBURG, PA 17120

Ref #
Invoice #
PO #
Dept #


TUE - 31 JAN A1
STANDARD OVERNIGHT

TRK# 7980 0196 7396

0201

17120
PA-US
MDT

ZN MDTA



512G18F59/A278

After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.